



m = 63.12
H = 553.00

m = 43.67
H = 553.54
Rv = 230
TI = 6.06
Fv = 0.141

m = 26.89
H = 552.78
Rv = 1000
TI = 3.74
Fv = 0.007

m = 17.37
H = 552.42
Rv = 150
TI = 1.68
Fv = 0.009

m = 0.77
H = 551.42
Rv = 20
TI = 0.50
Fv = 0.006

m = 77.65
H = 564.36
Rv = 2.00
TI = 0.050

m = 27.90
H = 553.77
Rv = 1.85
TI = 0.017

m = 66.64
H = 562.00
Rv = 200
TI = 1.77
Fv = 0.007

m = 55.13
H = 559.10
Rv = 2.86
TI = 0.041

m = 43.28
H = 550.97
Rv = 3.40
TI = 0.061

m = 20.00
H = 550.00
Rv = 400
TI = 0.003

m = 10.00
H = 549.17
Rv = 100
TI = 0.003

